

8 of many

We suggest that you consider establishing baseline information for the water quality of your well. Without this information it would be impossible to prove that the mine had caused any damage. You would probably want to take a series of samples over about a year, and you should ensure that the samples were taken properly, that the right preservatives and types of containers were used, that holding time requirements were met, and that the chain of custody was documented. If you have concerns about air quality, you should probably check with the Division of Air Quality about how to establish baseline information.

I will be in your area this week and will stop by to talk with you if you like.



Last account activity: 50 minutes ago

[Show details](#)